

Identify Operational Usage Cycles-Per-Hour:  
 1-6 Operational \_\_\_\_\_  
 Cycles-Per-Hour \_\_\_\_\_  
 7-19 Operational \_\_\_\_\_  
 Cycles-Per-Hour \_\_\_\_\_  
 20-Above Operational \_\_\_\_\_  
 Cycles-Per-Hour \_\_\_\_\_

Next Inspection Date (Estimated): \_\_\_\_\_  
 and Flight Hours (Estimated): \_\_\_\_\_

Magnetic Particle Inspection (MPI) Results  
 (this inspection): Passed \_\_\_\_\_  
 Failed \_\_\_\_\_

If a crack is found, indicate the approximate  
 location on the part and the length of the  
 crack in inches: \_\_\_\_\_

Total Time-In-Service (TIS) (Hours):  
 Estimated \_\_\_\_\_  
 Actual \_\_\_\_\_  
 Unknown \_\_\_\_\_  
 At Retirement \_\_\_\_\_

Inspection results at retirement (if known):  
 MPI Passed \_\_\_\_\_ Failed \_\_\_\_\_  
 Visual Passed \_\_\_\_\_ Failed \_\_\_\_\_

Log Book Entry for Part No. \_\_\_\_\_,  
 Serial No. \_\_\_\_\_, is (date) \_\_\_\_\_,  
 at Retirement Hours \_\_\_\_\_. This  
 part's Serial No. has been marked  
 unworthy and unfit for further service on  
 (date) \_\_\_\_\_, 199 \_\_\_\_.

Issued in Fort Worth, Texas, on December  
 13, 1995.

Daniel P. Salvano,  
*Manager, Rotorcraft Directorate, Aircraft  
 Certification Service.*

[FR Doc. 95-30771 Filed 12-19-95; 8:45 am]

BILLING CODE 4910-13-U

#### 14 CFR Part 39

[Docket No. 95-SW-21-AD; Amendment  
 39-9466; AD 95-26-08]

**Airworthiness Directives; Sikorsky  
 Aircraft Model S-58A, S-58B, S-58C,  
 S-58D, S-58E, S-58F, S-58G, S-58H,  
 S-58J, S-58BT, S-58DT, S-58ET, S-  
 58FT, S-58HT, and S-58JT Helicopters**

**AGENCY:** Federal Aviation  
 Administration, DOT.

**ACTION:** Final rule; request for  
 comments.

**SUMMARY:** This amendment adopts a  
 new airworthiness directive (AD) that is  
 applicable to Sikorsky Aircraft Model  
 S-58A, S-58B, S-58C, S-58D, S-58E,  
 S-58F, S-58G, S-58H, S-58J, S-58BT,  
 S-58DT, S-58ET, S-58FT, S-58HT, and  
 S-58JT helicopters. This action requires  
 initial and repetitive magnetic particle  
 inspections of the main rotor shaft  
 (shaft) for cracks, and defines power  
 limitations for certain helicopter  
 operations. This amendment is  
 prompted by a recent accident in which  
 a shaft failed, resulting in loss of power.  
 Subsequent inspections on other aircraft  
 of the same type revealed cracks in four  
 additional shafts. The actions specified  
 in this AD are intended to prevent

failure of the shaft, loss of power to the  
 rotor system, and subsequent loss of  
 control of the helicopter.

**DATES:** Effective January 4, 1996.

Comments for inclusion in the Rules  
 Docket must be received on or before  
 February 20, 1996.

**ADDRESSES:** Submit comments in  
 triplicate to the Federal Aviation  
 Administration (FAA), Office of the  
 Assistant Chief Counsel, Attention:  
 Rules Docket No. 95-SW-21-AD, 2601  
 Meacham Blvd., Room 663, Fort Worth,  
 Texas 76137.

**FOR FURTHER INFORMATION CONTACT:** Mr.  
 Francis X. Walsh, Aerospace Engineer,  
 FAA, Boston Aircraft Certification  
 Office, 12 New England Executive Park,  
 Burlington, Massachusetts 01803-5299,  
 telephone (617) 238-7158, fax (617)  
 238-7199.

**SUPPLEMENTARY INFORMATION:** This  
 amendment adopts a new AD that is  
 applicable to Sikorsky Aircraft Model  
 S-58A, S-58B, S-58C, S-58D, S-58E,  
 S-58F, S-58G, S-58H, S-58J, S-58BT,  
 S-58DT, S-58ET, S-58FT, S-58HT, and  
 S-58JT helicopters with shaft assembly,  
 part number (P/N) S1635-20059-2,  
 installed. This AD is prompted by an  
 accident in which the failure of a shaft  
 resulted in the crash of a helicopter.  
 Since that accident, inspections have  
 revealed cracks in four additional shafts.  
 The shaft transmits power to the main  
 rotor system to provide lift for the  
 helicopter. Failure of this shaft results  
 in loss of power to the main rotor  
 system and subsequent loss of control of  
 the helicopter. Due to the criticality of  
 the shaft, this AD must be issued  
 immediately to correct an unsafe  
 condition in the affected helicopters.

Since an unsafe condition has been  
 identified that is likely to exist or  
 develop on other Sikorsky Aircraft  
 Model S-58A, S-58B, S-58C, S-58D, S-  
 58E, S-58F, S-58G, S-58H, S-58J, S-  
 58BT, S-58DT, S-58ET, S-58FT, S-  
 58HT, and S-58JT helicopters of the  
 same type design, this AD is being  
 issued to prevent failure of the shaft,  
 loss of power to the rotor system, and  
 subsequent loss of control of the  
 helicopter. This AD requires  
 determining the operational cycles-per-  
 hour on the helicopters, removing the  
 shaft assembly from the main gear box,  
 and inspecting the shaft for cracks using  
 a magnetic particle inspection method  
 within the next 50 hours time-in-service  
 (TIS). Following this initial inspection,  
 repetitive magnetic particle inspections  
 are required. Additionally, this AD  
 prescribes operating limitations for  
 certain helicopter operations.

Since a situation exists that requires  
 the immediate adoption of this

regulation, it is found that notice and  
 opportunity for prior public comment  
 hereon are impracticable, and that good  
 cause exists for making this amendment  
 effective in less than 30 days.

#### Comments Invited

Although this action is in the form of  
 a final rule that involves requirements  
 affecting flight safety and, thus, was not  
 preceded by notice and an opportunity  
 for public comment, comments are  
 invited on this rule. Interested persons  
 are invited to comment on this rule by  
 submitting such written data, views, or  
 arguments as they may desire. Commu-  
 nications should identify the  
 Rules Docket number and be submitted  
 in triplicate to the address specified  
 under the caption **ADDRESSES**. All  
 communications received on or before  
 the closing date for comments will be  
 considered, and this rule may be  
 amended in light of the comments  
 received. Factual information that  
 supports the commenter's ideas and  
 suggestions is extremely helpful in  
 evaluating the effectiveness of the AD  
 action and determining whether  
 additional rulemaking action would be  
 needed.

Comments are specifically invited on  
 the overall regulatory, economic,  
 environmental, and energy aspects of  
 the rule that might suggest a need to  
 modify the rule. All comments  
 submitted will be available, both before  
 and after the closing date for comments,  
 in the Rules Docket for examination by  
 interested persons. A report that  
 summarizes each FAA-public contact  
 concerned with the substance of this AD  
 will be filed in the Rules Docket.

Commenters wishing the FAA to  
 acknowledge receipt of their comments  
 submitted in response to this rule must  
 submit a self-addressed, stamped  
 postcard on which the following  
 statement is made: "Comments to  
 Docket No. 95-SW-21-AD." The  
 postcard will be date stamped and  
 returned to the commenter.

The regulations adopted herein will  
 not have substantial direct effects on the  
 States, on the relationship between the  
 national government and the States, or  
 on the distribution of power and  
 responsibilities among the various  
 levels of government. Therefore, in  
 accordance with Executive Order 12612,  
 it is determined that this final rule does  
 not have sufficient federalism  
 implications to warrant the preparation  
 of a Federalism Assessment.

The FAA has determined that this  
 regulation is an emergency regulation  
 that must be issued immediately to  
 correct an unsafe condition in aircraft,  
 and that it is not a "significant

regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

### **PART 39—AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

Authority: 49 USC 106(g), 40101, 40113, 44701.

#### **§ 39.13 [Amended]**

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

AD 95-26-08 Sikorsky Aircraft: Amendment 39-9466. Docket No. 95-SW-21-AD.

*Applicability:* Model S-58A, S-58B, S-58C, S-58D, S-58E, S-58F, S-58G, S-58H, S-58J, S-58BT, S-58DT, S-58ET, S-58FT, S-58HT, and S-58JT helicopters with main rotor shaft assembly (shaft assembly), part number (P/N) S1635-20059-2, installed, certificated in any category.

Note 1: The shaft assembly consists of a main rotor shaft, P/N S1635-20059; an upper end plug, P/N S1635-20153; and a lower end plug, P/N S1635-20154. The shaft assembly P/N (S1635-20059-2) is marked on the edge of the main rotor shaft lower flange.

Note 2: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (j) to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition, or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the

unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any helicopter from the applicability of this AD.

*Compliance:* Required as indicated, unless accomplished previously.

To prevent failure of the main rotor shaft (shaft) loss of power to the rotor system, and subsequent loss of control of the helicopter, accomplish the following:

(a) From available helicopter records, determine the maximum number of actual operational cycles-per-hour of the current shaft assembly since installation. An operational cycle is defined as one turnaround (external lift cycle) for external load operations, and as one takeoff and one landing for internal load operations. A turnaround is defined as picking up an external load, transporting that load to a drop-off point, releasing the load, and flying to the next load pickup point. If the maximum number of actual operational cycles-per-hour cannot be determined, use 25-operational cycles-per-hour as the maximum operational cycles-per-hour for purposes of this AD. Record the determined number of operational usage cycles-per-hour of the shaft assembly in the appropriate aircraft maintenance records.

(1) If the maximum operational cycles-per-hour has ever equaled or exceeded 20 cycles-per-hour, inspect in accordance with paragraph (b) of this AD within the next 50 hours time-in-service (TIS), unless previously accomplished within the last 200 hours TIS.

(2) If the maximum operational cycles-per-hour has never exceeded 19 cycles-per-hour, inspect the shaft in accordance with paragraph (b) of this AD within the next 50 hours TIS, unless previously accomplished.

(b) Remove the shaft assembly, P/N S1635-20059-2, from the main gear box. Remove the upper end plug, P/N S1635-20153 and lower end plug, P/N S1635-20154, from the shaft assembly, and conduct a magnetic particle inspection (MPI) of the shaft for cracks in accordance with MIL-STD-1949 or ASTM E-1444. Pay particular attention to the inside diameter of the 0.7515-0.7510-inch diameter dowel pin holes in the flange and adjacent flange surfaces.

Note 3: Section 2D of Sikorsky Aircraft Alert Service Bulletin 58B35-34, dated June 9, 1995, contains a procedure for conducting a MPI of the shaft (in agreement with MIL-STD-1949 or ASTM E-1444).

(c) Conduct repetitive MPI's of the shaft for cracks as follows:

(1) If the maximum operational cycles-per-hour has ever equaled or exceeded 20 cycles-per-hour, repeat the MPI at intervals not to exceed 250 hours TIS from the date of the last inspection.

(2) If the maximum operational cycles-per-hour exceeds 6 cycles-per-hour, but has always been less than 20 cycles-per-hour, repeat the MPI at 1,250 hours TIS, and thereafter at intervals not to exceed 250 hours TIS from the date of the last inspection. If the last inspection was accomplished between 1,000 hours TIS and 1,250 hours TIS, begin the repetitive inspections within 250 hours TIS from the date of the last inspection instead of at 1,250 hours TIS.

(3) If the maximum operational cycles-per-hour has never exceeded 6 cycles-per-hour, repeat the MPI at 1,250 hours TIS. If the last inspection was accomplished between 1,000 hours TIS and 1,250 hours TIS, repeat the MPI within 250 hours TIS from the date of the last inspection instead of at 1,250 hours TIS.

(d) Report all inspection results to the Manager, Boston Aircraft Certification Office, using the Attachment provided later in this AD. Reporting requirements have been approved by the Office of Management and Budget and assigned OMB control number 2120-0056.

(e) If no crack is discovered, replace the upper and lower end plugs and reinstall the shaft assembly into the main gearbox.

(f) If any crack is discovered on or before the shaft assembly reaches 2,500 hours TIS, replace the shaft assembly with an airworthy shaft assembly, P/N S1635-20059-2. If the replacement shaft has previously been in service, determine the maximum operational cycles-per-hour in accordance with paragraph (a) and inspect in accordance with this AD.

Note 4: In accordance with the applicable maintenance manual, 2,500 hours TIS is the mandatory retirement life for the shaft assembly, P/N S1635-20059-2.

(g) If the main rotor shaft assembly installed on the helicopter has ever equaled or exceeded 20 or more operational cycles-per-hour, insert the following restrictions into the Limitations section of the Rotorcraft Flight Manual:

(1) For turbine engine installations: "The main rotor shaft assembly installed on this helicopter has been operated at 20 or more cycles-per-hour. Engine power is restricted to maximum continuous power at 93%N<sub>r</sub>. Takeoff power operations are prohibited."

(2) For reciprocating engine installations: "The main rotor shaft assembly installed on this helicopter has been operated at 20 or more cycles-per-hour. Engine power is restricted to maximum continuous power at 2,500 RPM. Takeoff power operations are prohibited."

(h) If the main rotor shaft assembly installed on the helicopter has ever equaled or exceeded 20 or more operational cycles-per-hour, install on the instrument panel, adjacent to the pilot's engine (N<sub>r</sub> or RPM) tachometer, torque meter, or manifold pressure gauges, a placard made of material that is not easily erased, disfigured, or obscured that contains the following statement in lettering of 0.2 inch minimum height and stated in one or two lines:

(1) For turbine engine installations: "MAX PWR: 101% Q AT 93% N<sub>r</sub>"

(2) For reciprocating engine installations: "MAX PWR: 47.5 IN. HG at 2,500 RPM"

(i) Continue to record operational cycles-per-hour of the shaft assembly in the appropriate maintenance records. If operational cycles-per-hour increases on an affected shaft assembly to the extent that it places the shaft assembly into a higher cycles-per-hour usage group, the applicable requirements and limitations contained in this AD for the higher usage group apply to that shaft assembly. A replacement shaft assembly must comply with all requirements

and limitations of this AD as applicable. If the number of operational cycles-per-hour determined for a replacement shaft assembly does not equal or exceed 20 cycles-per-hour, the Rotorcraft Flight Manual limitation specified in paragraph (g) and the placard specified in paragraph (h) may be removed.

(j) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used when approved by the Manager, Boston Aircraft Certification Office, FAA, New England Region. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Boston Aircraft Certification Office.

Note 5: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Boston Aircraft Certification Office.

(k) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

(l) This amendment becomes effective on January 4, 1996.

#### Attachment—Inspection Results Report

The following information must be reported as soon as possible, but no later than 7 days after inspection, to: Manager, Boston Aircraft Certification Office, Engine and Propeller Directorate, Aircraft Certification Service, Federal Aviation Administration, 12 New England Executive Park, Burlington, MA 01803-5299, FAX: (617) 238-7199.

Operator/Repair Station \_\_\_\_\_  
Aircraft Model No. \_\_\_\_\_  
Aircraft Serial No. \_\_\_\_\_  
Date of Inspection \_\_\_\_\_  
Main Rotor Part No. \_\_\_\_\_  
Main Rotor Serial No. \_\_\_\_\_  
Type of Aircraft Utilization:  
Passenger Carry \_\_\_\_\_  
Utility/Construction \_\_\_\_\_  
Firefighting \_\_\_\_\_  
Logging \_\_\_\_\_  
Other \_\_\_\_\_

Identify Operational Usage Cycles-Per-Hour:

1-6 Operational Cycles-Per-Hour \_\_\_\_\_

7-19 Operational Cycles-Per-Hour \_\_\_\_\_

20-Above Operational Cycles-Per-Hour \_\_\_\_\_

Next Inspection Date (Estimated): \_\_\_\_\_

and Flight Hours (Estimated): \_\_\_\_\_

Magnetic Particle Inspection (MPI)  
Results (this inspection):

Passed \_\_\_\_\_ Failed \_\_\_\_\_

If a crack is found, indicate the approximate location on the part and the length of the crack in inches: \_\_\_\_\_

Total Time-In-Service (TIS) (Hours):

Estimated \_\_\_\_\_

Actual \_\_\_\_\_

Unknown \_\_\_\_\_

At Retirement \_\_\_\_\_

Inspection results at retirement (if known):

MPI Passed \_\_\_\_\_

Failed \_\_\_\_\_

Visual Passed \_\_\_\_\_

Failed \_\_\_\_\_

Log Book Entry for Part No. \_\_\_\_\_,

Serial No. \_\_\_\_\_, is (date)

\_\_\_\_\_, at Retirement Hours

\_\_\_\_\_. This part's Serial No.

has been marked unairworthy and

unfit for further service on (date)

\_\_\_\_\_, 199 \_\_\_\_.

Issued in Fort Worth, Texas, on December 13, 1995.

Daniel P. Salvano,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 95-30772 Filed 12-19-95; 8:45 am]

BILLING CODE 4910-13-U

#### 14 CFR Part 39

[Docket No. 95-NM-238-AD; Amendment 39-9465; AD 95-26-07]

#### Airworthiness Directives; Bombardier Model CL-600-2B19 (Regional Jet Series 100) Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD) that is applicable to certain Bombardier Model CL-600-2B19 series airplanes. This action requires revising the Limitations Section of the Airplane Flight Manual to provide the flight crew with procedures to check the travel range of the aileron. This action also requires inspection for damage of the shear pins of the aileron flutter damper and aileron hinge fittings, and various follow-on actions. This amendment is prompted by reports of failure of shear pins in the aileron flutter damper. The actions specified in this AD are intended to prevent damage to the aileron hinge fittings due to failed shear pins, which subsequently could cause reduced controllability of the airplane.

**DATES:** Effective January 4, 1996.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of January 4, 1996.

Comments for inclusion in the Rules Docket must be received on or before February 20, 1996.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 95-NM-238-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

The service information referenced in this AD may be obtained from Bombardier, Inc., Canadair, Aerospace Group, P.O. Box 6087, Station Centre-ville, Quebec H3C 3G9, Canada. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, New York Aircraft Certification Office, Engine and Propeller Directorate, 10 Fifth Street, Third Floor, Valley Stream, New York; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

#### FOR FURTHER INFORMATION CONTACT:

Franco Pieri, Aerospace Engineer, Airframe Branch, ANE-172, FAA, Engine and Propeller Directorate, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York 11581; telephone (516) 256-7526; fax (516) 568-2716.

**SUPPLEMENTARY INFORMATION:** Transport Canada Aviation, which is the airworthiness authority for Canada, recently notified the FAA that an unsafe condition may exist on certain Bombardier Model CL-600-2B19 (Regional Jet Series 100) series airplanes. Transport Canada Aviation advises that it has received reports indicating that the shear pins of the aileron flutter damper had failed. Investigation revealed that the shear pins had sheared off and migrated out, which subsequently damaged the aileron hinge fittings. This condition, if not corrected, could result in reduced controllability of the airplane.

Bombardier has issued Canadair Regional Jet Alert Service Bulletin S.B. A601R-27-058, Revision "A," dated September 8, 1995, which describes procedures for:

1. A visual inspection to detect damage of the shear link, the shear pin, and the aileron attachment fitting;

2. Repair of the aileron attachment fitting, if necessary;

3. For airplanes on which any damaged shear pin is found, removal of the aileron flutter dampers, the shear links, the pivots, and the attaching hardware;

4. For certain airplanes on which no damaged shear pin is found, repetitive visual inspections to detect damage of the shear link, the shear pin, and the aileron attachment fitting until the aileron flutter dampers are removed.